

# Hilltop

## *Comprehensive Facility Assessment (2015)*

**Built: 1979**

**Last Major Renovation: 2000**

### **Safety Security and Code Compliance**

- Buzzer system entry – not secured vestibule
- Security cameras needed
- PA system is inadequate
- No sprinkler system - Upgrade fire alarm system
- Security doors needed for barrier to the pool from the gym
- ADA upgrades

### **Capacity/Educational Adequacy**

- Convert existing spaces to classroom and therapy room
- Playgrounds need improvement (equipment and shade)
- Educational technology improvements are needed

### **Healthy Learning Environment**

- Replace, chillers, controls, air handlers and VAV boxes
- Replace VCT and carpet floor finishes in corridors, classroom, gym, cafeteria and office areas. Replace flooring in small restrooms
- Replace lighting throughout building
- Replace interior and exterior doors and replace hardware. Paint door frames
- Remove wall covering in corridors and paint
- Technology infrastructure upgrades are needed

❖ *Listed facility needs exceed the referendum funds for projects 2017-2022*