



Description East baseball dugout footing

Taken Date Uploaded By Brad Holland 06/17/2022 at 02:20 pm

Upload Date File Name



Description West softball dugout ready for concrete footing

Taken Date Uploaded By 06/17/2022 at 02:18 pm **Brad Holland Upload Date File Name**

06/17/2022 at 02:31 pm CD9B855C-8EA5-4F31-9753-233...



Description South baseball dugout footing

Upload Date

Taken Date Uploaded By 06/17/2022 at 02:19 pm **Brad Holland**

File Name

059E4B76-A8DE-4FF9-8D24-8E56...



Description North Softball dugout footing

06/17/2022 at 02:32 pm

Taken Date Uploaded By 06/17/2022 at 02:18 pm **Brad Holland**

Upload Date File Name





Description

Press box slab location

Taken DateUploaded By06/17/2022 at 02:17 pmBrad Holland

Upload Date File Name



Description

Demolished fencing around track and football field

Taken DateUploaded By
06/17/2022 at 02:17 pm
Brad Holland

Upload Date File Name

06/17/2022 at 02:31 pm 1C2F2E43-114E-4A5A-8446-98A7...




Description

Demolished fencing around track and football field

Taken DateUploaded By
06/17/2022 at 02:17 pm
Brad Holland

Upload Date File Name

06/17/2022 at 02:31 pm 6B25D3CC-0D64-4520-8C1C-D33...



Description

Unit D locker infill

Taken DateUploaded By06/17/2022 at 02:12 pmBrad Holland

Upload Date File Name

06/17/2022 at 02:31 pm 87B1A2CE-1BDA-4CB4-8385-B6C...





DescriptionUnit D locker infill

Taken DateUploaded By
06/17/2022 at 02:12 pm
Brad Holland

Upload Date File Name



DescriptionSecurity door opening from Unit C2 to Unit D2

Taken Date

Uploaded By

06/17/2022 at 02:10 pm

Brad Holland

Upload Date

File Name

06/17/2022 at 02:32 pm 245A94CD-D5E2-43FA-AF34-E353...



Security door opening from Unit D to Unit D2

Taken DateUploaded By06/17/2022 at 02:11 pmBrad Holland

Upload Date File Name



DescriptionSecurity door opening from Unit C to Unit B

Taken DateUploaded By06/17/2022 at 02:07 pmBrad Holland

06/17/2022 at 02:31 pm 069541C8-8A1C-4016-A356-EE43...

File Name

Upload Date





Description

Security door opening from Unit C to Unit D

Taken DateUploaded By
06/17/2022 at 02:07 pm
Brad Holland

Upload Date File Name



Description

Stage duct modifications

Taken Date

Uploaded By

06/17/2022 at 01:54 pm

Brad Holland

Upload Date

File Name

06/17/2022 at 02:32 pm 2056CA1F-733A-4F3E-9E0B-A2EB...



Description

Security door opening from Unit A to Unit B

Taken DateUploaded By
06/17/2022 at 02:07 pm
Brad Holland

Upload Date File Name

06/17/2022 at 02:31 pm 66A5E345-00F4-4B7C-97C5-1ED...



Description

Stage duct modifications

Taken DateUploaded By06/17/2022 at 01:54 pmBrad Holland

Upload Date File Name

06/17/2022 at 02:32 pm 3774422C-6B94-45E4-B28D-62A...





DescriptionEast gym North End

Taken DateUploaded By06/17/2022 at 01:51 pmBrad Holland

Upload Date File Name

06/17/2022 at 02:32 pm 10F261B4-08DE-4329-AF30-F331...

DescriptionEast locker room area

 Taken Date
 Uploaded By

 06/17/2022 at 01:50 pm
 Brad Holland

 Upload Date
 File Name

 06/17/2022 at 02:32 pm
 52CA61E3-A56C-4F66-9B9F-716...



_ . . .

East locker room area

Taken DateUploaded By06/17/2022 at 01:50 pmBrad Holland

Upload Date File Name

Description

East locker room area

Taken DateUploaded By06/17/2022 at 01:50 pmBrad Holland

Upload Date File Name

06/17/2022 at 02:31 pm 39D93E70-20BB-439B-8561-FD9...





Description

Concession building under drains

Taken Date 06/17/2022 at 09:49 am

Upload Date 06/17/2022 at 02:32 pm

09:49 am Brad Holland

File Name

Uploaded By

1C50A4C2-FB60-47AA-B184-00C...



Description

Concession building under drains

Taken Date

06/17/2022 at 09:49 am

Upload Date

06/17/2022 at 02:32 pm

Uploaded By

Brad Holland

File Name

0A2D71FA-068C-4053-9F81-C0A...